





What's new Organisation Publications Contact Links Members

Home Inspection Database

Inspections Inspection database | Inspection details

Detentions MSC DONATA

Bannings

Appeal procedure

Target Factor Date of

Facts & Figures

New inspection regime

Inspection details:

Date of first boarding: 13/08/2009

Date of final

boarding: 13/08/2009

Port of inspection: Le Havre (PA), France.

Type of inspection : **Initial inspection**

Nb of deficiency(ies)

:

Ship's particulars at the time of inspection:

IMO number : **9237151**

Name: MSC DONATA

Flag: Panama Callsign: 3EOS8

Ship type: **Containership**

Gross tonnage: 40108 Keel date: 2002

Classification society:

- Class certificate issued by Germanischer Lloyd (GL), classification society responsable for issuance of class certificate as at date of first boarding

Statutory certificates:

- International Anti-fouling System Certificate is issued by

Germanischer Lloyd (GL)

- Safety management certificat (SMC) is issued by Germanischer Lloyd (GL)
- Doc.of compliance dangerous goods is issued by Germanischer Lloyd (GL)
- International sewage pollution prevention certific is issued by Germanischer Lloyd (GL)
- Document of compliance (DoC) is issued by Bureau Veritas (BV) last survey in Hong Kong, China on 14/01/2009 by Bureau Veritas (BV)
- International Air Pollution Prevention Cert is issued by Germanischer Lloyd (GL) last survey in Taiwan, China on 13/10/2008 by Germanischer Lloyd (GL)
- Oil pollution prevention (iopp) is issued by Germanischer Lloyd (GL) last survey in Taiwan, China on 13/10/2008 by Germanischer Lloyd (GL)
- Load lines certificates is issued by Germanischer Lloyd (GL) last survey in Taiwan, China on 13/10/2008 by Germanischer Lloyd (GL)
- Cargo ship safety equipment is issued by Germanischer Lloyd (GL) last survey in Taiwan, China on 13/10/2008 by Germanischer Lloyd (GL)
- Cargo ship safety construction is issued by Germanischer Lloyd (GL) last survey in Taiwan, China on 13/10/2008 by Germanischer Lloyd (GL)
- Cargo ship safety radio is issued by Germanischer Lloyd (GL) last survey in Taiwan, China on 13/10/2008 by Germanischer Lloyd (GL)

Ship manager

- MSC Ship Management HK Ltd, Hong Kong, China

Areas inspected:

- Engine and steering room

Back to list

Disclaimer:

The Paris MOU (its member authorities, the secretariat and the SIReNaC manager) will not be held liable for any loss, damage, or harm resulting from the use of information contained in this database, or of any reliance on its accuracy, completeness or timeliness.



Hosted by DSI - France - version: R1-4-1