

AQUADONNA**Inspection details :**

Date of first boarding : **20/07/2010**
 Date of final boarding : **24/07/2010**
 Port of inspection : **Vancouver, Canada.**
 Type of inspection : **Expanded inspection**
 Nb of deficiency(ies) : **16**
 Nb of deficiency(ies) ground(s) for detention : **5**
 Duration of detention : **5 days**

Ship's particulars at the time of inspection :

IMO number : **9075668**
 Name : **AQUADONNA**
 Flag : **Liberia**
 Callsign : **A8TW9**
 Ship type : **Bulk carrier**
 Gross tonnage : **81272**
 Keel date : **1995**

Classification society :

- Class certificate issued by American Bureau of Shipping (ABS), classification society responsible for issuance of class certificate as at date of first boarding

Statutory certificates :

- International Air Pollution Prevention Cert is issued by American Bureau of Shipping (ABS)
- Cargo ship safety equipment is issued by American Bureau of Shipping (ABS)
- Cargo ship safety construction is issued by American Bureau of Shipping (ABS) last survey in Canada by American Bureau of Shipping (ABS)
- Cargo ship safety radio is issued by American Bureau of Shipping (ABS) last survey in Canada by American Bureau of Shipping (ABS)
- Document of compliance (DoC) is issued by Registro Italiano Navale (RINA)
- Safety management certificat (SMC) is issued by Registro Italiano Navale (RINA)
- Load lines certificates is issued by American Bureau of Shipping (ABS)
- Oil pollution prevention (iopp) is issued by American Bureau of Shipping (ABS)

Ship manager

- C Transport Maritime SAM, Monaco

Areas inspected :

- Accommodation and galley
- Ballast tanks
- Cargo holds / tanks
- Engine and steering room
- Navigation bridge
- Outside decks and forecastle

Operational controls carried out

- Abandon ship drill
- Communication equipment
- Emergency fire pump
- Emergency generator

- Emergency steering
- Fire drill
- 15 ppm OWS tested

Deficiencies :

- Alarm signals, Boiler alarm, Malfunctioning, ground for detention
- Fire safety measures, Fire fighting equipment and appliances
- Fire safety measures, Fire patrol
- Fire safety measures, Fire patrol
- Fire safety measures, Fire-dampers, Not as required, ground for detention
- Fire safety measures, Other (fire safety)
- ISM related deficiencies, Maintenance of the ship and equipment, Not according SMS, ground for detention
- Load lines , Covers (hatchway-, portable-, tarpaulins, etc.)
- MARPOL annex I, Oil record book
- MARPOL annex VI, Other(MARPOL Annex-VI)
- Propulsion & aux., Other (machinery)
- Propulsion & aux., Other (machinery), Other, ground for detention
- Safety of navigation, Charts
- Safety of navigation, Magnetic compass
- Working spaces and accident prevention, Electrical

[Back to list](#)

Disclaimer:

The Paris MOU (its member authorities, the secretariat and the SIRENaC manager) will not be held liable for any loss, damage, or harm resulting from the use of information contained in this database, or of any reliance on its accuracy, completeness or timeliness.



Hosted by DSI - France - version : R1-4-1