

Public Site Inspection Portlet(1.5.2.1@24.01.2011\_14:51)

Search

Inspections Details

Ship Details

**IMO Number** 9185920 **Name** MTM WEST PORT **Flag** Hong Kong, China  
**Type** Chemical tanker **Gross Tonnage** 11951 **Keel Laying Date** 01/01/1999 12 Years

ISM Company

**IMO Number** 1314037 **Address** **Country**  
**Name** MTM Ship Management Pte Ltd **City**

Charterers

Type	Name	Address	City	Country
Voyage charterer	TRANSAMMONIA TRAMMO TRADING AG	Bahnestasse 1	Aldendorf	Switzerland

Class Certificates

issuingAuthority	issue date	expiry date
NKK	09/04/2010	14/03/2015

Statutory Certificates

Certificate	Issuing authority	issue date	expiry date	Surveying authority	Date of last survey	Place of last survey
Document of Compliance	ABS	17/11/2009	16/09/2011			
Minimum Safe Manning Document	Hong Kong, China	20/02/2010				
Cargo Ship Safety Radio	NKK	19/04/2010	14/03/2015			
International Air Pollution Prevention	NKK	19/04/2010	14/03/2015			
International Sewage Pollution Prevention	NKK	19/04/2010	14/03/2015			
Dangerous Chemicals in Bulk (CoF/IBC Code)	NKK	19/04/2010	14/03/2015			
Cargo Ship Safety Construction	NKK	25/05/2010	24/10/2010			
Cargo Ship Safety Equipment	NKK	25/05/2010	24/10/2010			
Prevention of Pollution by Oil	NKK	25/05/2010	24/10/2010			
Load Line	NKK	25/05/2010	24/10/2010			
Tonnage	NKK	25/05/2010				
Safety Management Certificate	ABS	24/07/2010	23/07/2015			
International Ship Security	ABS	24/07/2010	23/07/2015			

Inspection Details

**Type of Inspection** PSC - More Detailed Inspection **Date of first visit** 01/09/2010 **Nb. of Deficiencies** 2  
**Place of Inspection** Klaipeda **Data of final visit** 01/09/2010 **Nb. of Deficiencies ground for detention**

Inspected Areas

**Inspected Areas** Accommodation and galley  
 Engine and steering room  
 Navigation bridge  
 Outside decks and forecastle

Operational Controls

**Operational Controls Carried Out** Emergency fire pump  
 Emergency generator  
 Emergency steering  
 15 ppm OWS tested

**Deficiencies**

<b>Area</b>	<b>Defective item</b>	<b>Nature of defect</b>	<b>Ground for detention</b>	<b>RO Related</b>
Certificate & Documentation - Documents	01315 - Oil record book	Not properly filled	No	No
Living and Working Conditions - Working Conditions	09205 - Safe means of access Shore - Ship	Not as required	No	No