

ADRIAN

Inspection details :

Date of first boarding : **28/07/2010**
Date of final boarding : **30/07/2010**
Port of inspection : **Rotterdam, Netherlands.**
Type of inspection : **More detailed inspection**
Nb of deficiency(ies) : **21**
Nb of deficiency(ies) ground(s) for detention : **4**
Duration of detention : **3 days**

Ship's particulars at the time of inspection :

IMO number : **9123221**
Name : **ADRIAN**
Flag : **Liberia**
Callsign : **A8NR5**
Ship type : **Containership**
Gross tonnage : **16799**
Keel date : **1997**

Classification society :

- Class certificate issued by Germanischer Lloyd (GL), classification society responsible for issuance of class certificate as at date of first boarding

Statutory certificates :

- Cargo ship safety equipment is issued by Germanischer Lloyd (GL)
- Document of compliance (DoC) is issued by Germanischer Lloyd (GL)
- International sewage pollution prevention certific is issued by Germanischer Lloyd (GL)
- International Air Pollution Prevention Cert is issued by Germanischer Lloyd (GL) last survey in Germany on 29/07/2009 by Germanischer Lloyd (GL)
- Oil pollution prevention (iopp) is issued by Germanischer Lloyd (GL) last survey in Germany on 29/07/2009 by Germanischer Lloyd (GL)
- Cargo ship safety construction is issued by Germanischer Lloyd (GL) last survey in Germany on 29/07/2009 by Germanischer Lloyd (GL)
- Cargo ship safety radio is issued by Germanischer Lloyd (GL) last survey in Germany on 15/07/2009 by Germanischer Lloyd (GL)
- Load lines certificates is issued by Germanischer Lloyd (GL) last survey in Germany on 15/07/2009 by Germanischer Lloyd (GL)

Ship manager

- Komrowski Befrachtungskontor, Germany

Areas inspected :

- Accommodation and galley
- Engine and steering room
- Navigation bridge
- Outside decks and forecastle

Operational controls carried out

- Emergency fire pump
- Emergency generator
- Emergency steering

- 15 ppm OWS tested

Deficiencies :

- Accommodation, Lighting
- Accommodation, Ventilation
- Alarm signals, Machinery controls alarm
- Fire safety measures, Doors within main vertical zone
- Fire safety measures, Fire detection
- Fire safety measures, Fire-dampers, Not as required, ground for detention
- ISM related deficiencies, Emergency preparedness, Not according SMS, ground for detention
- ISM related deficiencies, Maintenance of the ship and equipment, Not according SMS, ground for detention
- Life saving appliances , Inflatable liferafts
- Life saving appliances , Lifeboats
- Life saving appliances , Lifebuoys
- Life saving appliances , Lifejackets
- Life saving appliances , Lifejackets
- Life saving appliances , Rescue boats
- Load lines , Cargo & other hatchways
- Load lines , Windows, side scuttles
- MARPOL annex I, Oil filtering equipment, Not as required, ground for detention
- Operational deficiencies, Evaluation of crew performance
- Operational deficiencies, Manuals instructions, etc.
- Operational deficiencies, Other (SOLAS operational)
- Working spaces and accident prevention, Ventilation

[Back to list](#)

Disclaimer:

The Paris MOU (its member authorities, the secretariat and the SIRENaC manager) will not be held liable for any loss, damage, or harm resulting from the use of information contained in this database, or of any reliance on its accuracy, completeness or timeliness.



Hosted by DSI - France - version : R1-4-1