

Public Site Inspection Portlet(1.5.2.1@24.01.2011_14:51)

Search

Inspections Details

Ship Details

IMO Number 8602385 **Name** BOE OCEAN **Flag** Malta
Type General cargo/multipurpose **Gross Tonnage** 6425 **Keel Laying Date** 01/01/1988 23 Years

ISM Company

IMO Number 4078121 **Address** **Country**
Name WEM Lines SA **City**

Class Certificates

issuingAuthority	issue date	expiry date
BV	13/06/2009	11/06/2014

Statutory Certificates

Certificate	Issuing authority	issue date	expiry date	Surveying authority	Date of last survey	Place of last survey
Tonnage	Malta	20/12/2004				
Continuous Synopsis Record	Malta	24/12/2004	24/12/2014			
Safety Management Certificate	NKK	28/06/2005	01/05/2010	NKK	29/09/2007	Greece
International Ship Security	NKK	26/07/2005	01/05/2010	NKK	29/09/2007	Greece
Document of Compliance	NKK	12/09/2006	31/08/2011	NKK	06/11/2009	Greece
International Anti-Fouling System	BV	29/09/2007	29/09/2017			
Minimum Safe Manning Document	Malta	25/04/2008	24/04/2013			
Prevention of Pollution by Oil	BV	13/06/2009	11/06/2014			
International Air Pollution Prevention	BV	13/06/2009	11/06/2014			
Load Line	BV	13/06/2009	11/06/2014			

Inspection Details

Type of Inspection PSC - More Detailed Inspection **Date of first visit** 17/02/2010 **Nb. of Deficiencies** 11
Place of Inspection Dunkerque (GPM) **Data of final visit** 26/02/2010 **Nb. of Deficiencies ground for detention** 1

Inspected Areas

Inspected Areas Accommodation and galley
Ballast tanks
Engine and steering room
Navigation bridge
Outside decks and forecastle

Operational Controls

Operational Controls Carried Out Other
Abandon ship drill
Communication equipment
Emergency fire pump
Emergency generator
Fire drill
15 ppm OWS tested

Deficiencies

Area	Defective item	Nature of defect	Ground for detention	RO Related
Fire safety	07115 - Fire-dampers	Inoperative	Yes	No
Safety of Navigation	10116 - Nautical publications	Not up to date	No	No
ISM	15110 - Documentation-ISM	Not according SMS	No	No
Certificate & Documentation - Documents	01315 - Oil record book	Not properly filled	No	No
Water/Weathertight conditions	03105 - Covers (hatchway-, portable-, tarpaulins, etc.)	Not as required	No	No
Structural Conditions	02115 - Bulkheads - operational damage	Damaged	No	No
Safety of Navigation	10128 - Navigation bridge visibility	Not as required	No	No
ISM	15102 - Company responsibility and authority	Missing	No	No
Fire safety	07118 - International shore-connection	Not as required	No	No
Living and Working Conditions - Working Conditions	09229 - Winches & capstans	Not properly maintained	No	No
Living and Working Conditions - Working Conditions	09231 - Other (mooring)	Other	No	No

Detention Details

Reason **Date of Detention** 17/02/2010
Allowed to proceed to agreed repair yard **Date of Release** 26/02/2010 9 Days

Refusal Of Access

inspection led to refusal of access

Reason