Home Current detentions Preventions of operation Refusal of access Inspections Calculators

Public Site Inspection Portlet(1.5.2.1@24.01.2011\_14:51)

Search

Inspections Details

Ship Details —

Туре

IMO Number 9388429 Name HARLEQUIN Flag Panama

Gas carrier Gross Tonnage 4306 Keel Laying Date 01/01/2005 6 Years

ISM Company \_\_

IMO Number 1185781 Address Country

Name Thome Ship Management Pte Ltd City

Class Certificates -

issuingAuthority	issue date	expiry date
NKK	28/11/2006	24/09/2011

## Statutory Certificates

Certificate	Issuing authority	issue date	expiry date	Surveying authority	Date of last survey	Place of last survey
Minimum Safe Manning Document	Panama	21/08/2006				
Tonnage	NKK	25/09/2006				
Cargo Ship Safety Construction	NKK	15/01/2007	24/09/2011	NKK	19/09/2009	Norway
International Air Pollution Prevention	NKK	15/01/2007	24/09/2011	NKK	19/09/2009	Norway
International Sewage Pollution Prevention	NKK	15/01/2007	24/09/2011			
Load Line	NKK	15/01/2007	24/09/2011	NKK	19/09/2009	Norway
Liquified Gases in Bulk (CoF/IGC Code)	NKK	15/01/2007	24/09/2011	NKK	19/09/2009	Norway
International Anti-Fouling System	NKK	21/02/2007	21/02/2012			
International Ship Security	Panama	30/03/2007	16/03/2012	NKK	05/02/2010	France
Safety Management Certificate	NKK	26/06/2007	15/03/2012	NKK	10/03/2010	France
Prevention of Pollution by NLS in Bulk	NKK	30/07/2007	24/09/2011	NKK	19/09/2009	Norway
Prevention of Pollution by Oil	NKK	15/11/2007	24/09/2011	NKK	19/09/2009	Norway
Document of Compliance	DNV	13/10/2008	13/10/2013	DNV	07/10/2009	Singapore
Cargo Ship Safety Radio	NKK	30/10/2008	24/09/2011	NKK	19/09/2009	Norway

Inspection Details

Type of Inspection PSC - More Detailed Inspection Date of first visit 26/05/2010 Nb. of Deficiencies

Place of Inspection Dunkerque (GPM) Data of final visit 26/05/2010 Nb. of Deficiencies ground for detention

Inspected Areas

Inspected Areas Engine and steering room

Navigation bridge Outside decks and forecastle

Operational Controls —

Operational Controls Carried Out Other

Emergency generator

Deficiencies

Area Defective item		Defective item	Nature of defect	Ground for detention	RO Related	
	Safety of Navigation	10111 - Charts	Not up to date	No	No	
	Propulsion and auxiliary machinery	13107 - Other (machinery)	Other	No	No	

