





What's New Organisation Contact Links Members High Level Forum

Home

Banned ships

**Current Detentions** 

Detention list

Detained ships in the spotlight

**Inspection Database** 

Appeal procedure

Caught in the Net

Target Factor

Code of Good Practice

Expanded Inspection information

Inspection database | Inspection details

## **PANTELIS**

Inspection details:

Date of first

boarding:

Date of final

boarding:

27/10/2006

27/10/2006

Port of inspection

1

Initial inspection

Primorsk, Russian Federation.

Type of inspection

:

Nb of deficiency(ies):

ienciency (ies):

Ship's particulars at the time of inspection:

IMO number: 9274616
Name: PANTELIS
Flag: Cyprus
Callsign: P3UJ9

Ship type: Oil tanker
Gross tonnage: 62877

Keel date : 2004

# **Classification society:**

- Class certificate issued by Det Norske Veritas (DNVC), classification society responsable for issuance of class certificate as at date of first boarding

## Statutory certificates:

- International ship security certificate is issued by Det Norske Veritas (DNVC)
- Cargo ship safety equipment is issued by Det Norske Veritas (DNVC) last survey in Greece on 10/07/2006 by Det Norske Veritas (DNVC)
- Cargo ship safety construction is issued by Det Norske Veritas (DNVC) last survey in United States of America. on 10/07/2006 by Det Norske Veritas (DNVC)
- Cargo ship safety radio is issued by Det Norske Veritas (DNVC) last survey in United States of America. on 10/07/2006 by Det Norske Veritas (DNVC)
- Oil pollution prevention (iopp) is issued by Det Norske Veritas (DNVC) last survey in United States of America. on 10/07/2006 by Det Norske Veritas (DNVC)
- Load lines certificates is issued by Det Norske Veritas (DNVC) last survey in United States of America. on 10/07/2006 by Det Norske Veritas (DNVC)
- Tonnage certificate is issued by Det Norske Veritas (DNVC) last survey in Greece on 08/07/2004 by Det Norske Veritas (DNVC)

## Ship manager

- ENESEL, Kolonaki International Center, 23a, Vasilissis Sofias Avenue, Athens, Greece

#### Charterer

- LITASCO, Geneva, Switzerland

### Areas inspected:

- Accommodation and galley
- Navigation bridge

### Operational controls carried out

- Abandon ship drill
- Communication equipment
- Emergency fire pump

### Back to list

#### Disclaimer:

The Paris MOU (its member authorities, the secretariat and the SIReNaC manager) will not be held liable for any loss, damage, or harm resulting from the use of information contained in this database, or of any reliance on its accuracy, completeness or timeliness.

