



[Home](#)

[Banned ships](#)

[Current Detentions](#)

[Detention list](#)

[Detained ships in the spotlight](#)

Inspection Database

[Appeal procedure](#)

[Caught in the Net](#)

[Target Factor](#)

[Code of Good Practice](#)

[Expanded Inspection information](#)

[Inspection database](#) | [Inspection details](#)

HANJIN MADRID

Inspection details :

Date of first boarding : **12/03/2007**
Date of final boarding : **12/03/2007**
Port of inspection : **Le Havre (PA), France.**
Type of inspection : **Initial inspection**
Nb of deficiency(ies) : **1**

Ship's particulars at the time of inspection :

IMO number : **9248150**
Name : **HANJIN MADRID**
Flag : **Germany**
Callsign : **DHQS**
Ship type : **Containership**
Gross tonnage : **65918**
Keel date : **2003**

Classification society :

- Class certificate issued by Germanischer Lloyd (GL), classification society responsible for issuance of class certificate as at date of first boarding

Ship manager

- NSB NIEDERELBE, 47-51, Harburgerstrasse, Buxtehude, Germany

Areas inspected :

- Engine and steering room

Deficiencies :

- Crew certificates, Other (STCW)

[Back to list](#)

Disclaimer:

The Paris MOU (its member authorities, the secretariat and the SIRENaC manager) will not be held liable for any loss, damage, or harm resulting from the use of information contained in this database, or of any reliance on its accuracy, completeness or timeliness.



Hosted by DSI - France - version : R1-4-1