



on Port State Control



**What's new**   **Organisation**   **Publications**   **Contact**   **Links**   **Members**

[Home](#)

**Inspections**

[Detentions](#)

[Bannings](#)

[Appeal procedure](#)

[Target Factor](#)

[Facts & Figures](#)

[New inspection regime](#)

[Inspection Database](#)

[Inspection database](#) | [Inspection details](#)

## **CHIBERTA**

### **Inspection details :**

Date of first boarding : **27/07/2009**  
Date of final boarding : **27/07/2009**  
Port of inspection : **Lisbon, Portugal.**  
Type of inspection : **Initial inspection**  
Nb of deficiency(ies) : **3**

### **Ship's particulars at the time of inspection :**

IMO number : **9333814**  
Name : **CHIBERTA**  
Flag : **France**  
Callsign : **FMLN**  
Ship type : **Chemical tanker**  
Gross tonnage : **11799**  
Keel date : **2006**

### **Classification society :**

- Class certificate issued by Bureau Veritas (BV), classification society responsible for issuance of class certificate as at date of first boarding

### **Statutory certificates :**

- Load lines certificates is issued by Bureau Veritas

(BV) last survey in France on 22/10/2008 by Bureau Veritas (BV)

Ship manager

- Petromarine SA, France

Charterer

- CSSA- Charter. and Ship. Servi, Geneva, Geneva, Switzerland

Areas inspected :

- Accommodation and galley
- Engine and steering room
- Navigation bridge
- Outside decks and forecastle

Deficiencies :

- Crew certificates, Certificate for personnel on tankers
- Life saving appliances , Stowage of liferafts
- Ship's certificates and documents , Conformance Test Report

[Back to list](#)

Disclaimer:

The Paris MOU (its member authorities, the secretariat and the SIRENaC manager) will not be held liable for any loss, damage, or harm resulting from the use of information contained in this database, or of any reliance on its accuracy, completeness or timeliness.



*Hosted by DSI - France - version : R1-4-1*