Home Current detentions Preventions of operation Refusal of access Inspections Ship Risk Profile

Public Site Inspection Portlet(1.5.1@07.12.2010_11:22)					
Search					
Inspections	Details				
Ship Details					
IMO Numbe	er 8608200	Name	MSC LEVINA	Flag	Panama
Туре	Containe	Gross Tonnage	36420	Keel Laying Date	01/01/1988 23 Years
ISM Compar	iy				
IMO Numbe	er		Addr	ess 45th FLOOR, 1	THE CENTRE 99, QUEENS ROAD CENTRAL Country Hong Kong, China
Name	MEDITER	Ranean Shipping CC	OMPANY City	HONG KONG	
_ Class Certific	ates				

issuingAuthority	issue date	expiry date	
RINA	20/05/2003	19/05/2008	

Statutory Certificates

Certificate	Issuing authority	issue date	expiry date	Surveying authority	Date of last survey	Place of last survey
Minimum Safe Manning Document	Panama	23/07/2002				
Tonnage	RINA	05/03/2004				
Load Line	RINA	19/03/2004	31/03/2008	RINA	10/01/2007	Belgium
Cargo Ship Safety Construction	RINA	20/05/2005	31/05/2008	RINA	10/01/2007	Belgium
Document of Compliance Dangerous Goods	RINA	08/06/2005	31/03/2008			
International Air Pollution Prevention	RINA	06/09/2005	31/03/2008	RINA	10/01/2007	Belgium
Safety Management Certificate	RINA	18/12/2006	17/11/2011			
Cargo Ship Safety Equipment	RINA	10/01/2007	10/01/2008			
Cargo Ship Safety Radio	RINA	06/02/2007	10/01/2008			
Prevention of Pollution by Oil	RINA	06/02/2007	31/03/2008			
Document of Compliance	BV	07/02/2007	19/10/2011			

ſ	_ Inspection Details	section Details						
	Type of Inspection	PSC - Initial Inspection	Date of first visit	06/09/2007	Nb. of Deficiencies			
	Place of Inspection	Antwerp	Data of final visit	06/09/2007	Nb. of Deficiencies ground for detention			

Inspected Areas

Inspected Areas Accommodation and galley Engine and steering room Navigation bridge Outside decks and forecastle



© European Maritime Safety Agency, 2010 (1.5.1@07.12.2010_11:19)