# Home Current detentions Preventions of operation Refusal of access Inspections Calculators

Search

Inspections D	etails						
Ship Details							
IMO Number	9468293	Name	NYK Adonis	Flag	Panama		
Туре	Container	Gross Tonnage	105644	Keel Laying Date	01/01/2009 2 Years		
ISM Company							
IMO Number	1968365		Address	Country			
Name	NYK Shipmar	nagement Pte Ltd	City				
Charterers							
	Туре		r	lame	Address	City	Country
	Fime charterer		Ν	YK Line	Yusen Bldg 3-2, Marunouchi 2 -chome	Tokyo	Japan

# **Class Certificates**

issuingAuthority	issue date	expiry date
NKK	22/06/2010	29/03/2015

# Statutory Certificates

Certificate	Issuing authority	issue date	expiry date	Surveying authority	Date of last survey	Place of last survey
Document of Compliance	NKK	07/11/2008	11/06/2012	NKK	06/07/2010	Singapore
Minimum Safe Manning Document	Panama	05/02/2010				
International Anti-Fouling System	NKK	30/03/2010	30/03/2015			
Cargo Ship Safety Construction	NKK	17/06/2010	29/03/2015			
Cargo Ship Safety Equipment	NKK	17/06/2010	29/03/2015			
Cargo Ship Safety Radio	NKK	17/06/2010	29/03/2015			
International Air Pollution Prevention	NKK	17/06/2010	29/03/2015			
International Sewage Pollution Prevention	NKK	17/06/2010	29/03/2015			
Load Line	NKK	17/06/2010	29/03/2015			
Document of Compliance Dangerous Goods	NKK	17/06/2010	29/03/2015			
Safety Management Certificate	NKK	30/06/2010	29/11/2010			
International Ship Security	Panama	05/07/2010	30/06/2015			

# Inspection Details

Type of Inspection	PSC - Initial Inspection	Date of first visit	30/07/2010	Nb. of Deficiencies
Place of Inspection	Rotterdam	Data of final visit	30/07/2010	Nb. of Deficiencies ground for detention

# Inspected Areas

Inspected Areas Accommodation and galley Engine and steering room Navigation bridge Outside decks and forecastle

Paris MoU and EMSA assume no liability or responsibility for any errors or omissions resulting from (or pursuant to) errors or omissions in data submitted to or retrieved from the system.

