

Welcome!

- [Home](#)
- [Current detentions](#)
- [Preventions of operation](#)
- [Refusal of access](#)
- [Inspections](#)
- [Calculators](#)
- [Company Performance](#)







Search

- [Inspections](#)
- [Details](#)

Ships	Inspections	Detentions	ISM Deficiencies	Non-ISM Deficiencies	Bans
1	4	0	0	3	0

Deficiencies count, in the table above, exclude deficiencies marked as Accidental Damage

	IMO	Name	Flag	Type	Age	Date of Inspection	Type of inspection	Port of inspection	Number of Deficiencies	Result
9370422	STAR LILY	 Panama	Bulk carrier	8	25/08/2014	Initial inspection	Romania - Constanta	0		
9370422	STAR LILY	 Panama	Bulk carrier	6	05/12/2012	Initial inspection	Croatia - Rijeka	1		
9370422	STAR LILY	 Panama	Bulk carrier	5	17/12/2011	More detailed inspection	Netherlands - Rotterdam	2		
9370422	STAR LILY	 Panama	Bulk carrier	1	24/08/2009	Initial inspection	Russian Federation - Murmansk	0		

[SHOW ALL](#)

resulting from (or pursuant to) errors or omissions in data submitted to or retrieved from the system.

transmitted in any form, or by any means without prior authorisation in writing from the owners of the data.

p as per first visit date of inspection

