

[Home](#)**[Inspections](#)**[Detentions](#)[Bannings](#)[Appeal procedure](#)[Target Factor](#)[Facts & Figures](#)[New inspection regime](#)[Inspection Database](#)[Inspection database](#) | [Inspection details](#)**DUTCH EMERALD****Inspection details :**Date of first boarding : **05/10/2009**Date of final boarding : **05/10/2009**Port of inspection : **Klaipeda, Lithuania.**Type of inspection : **Expanded inspection**Nb of deficiency(ies) : **1****Ship's particulars at the time of inspection :**IMO number : **9191668**Name : **DUTCH EMERALD**Flag : **Netherlands**Callsign : **PCIP**Ship type : **Chemical tanker**Gross tonnage : **4670**Keel date : **1999****Classification society :**

- Class certificate issued by Lloyd's Register (LR), classification society responsible for issuance of class certificate as at date of first boarding

Statutory certificates :

- Document of compliance (DoC) is issued by Lloyd's Register (LR)
- Safety management certificat (SMC) is issued by Lloyd's Register (LR)
- International ship security certificate is issued by Lloyd's Register (LR)
- Cargo ship safety is issued by Lloyd's Register (LR) last survey in Netherlands on 11/07/2008 by Lloyd's Register (LR)

Ship manager

- Essberger JT BV, Netherlands

Charterer

- DOW EUROPE, 2 HEATHROW BLVD, WEST DRAYTON, United Kingdom

Areas inspected :

- Accommodation and galley
- Engine and steering room
- Navigation bridge
- Outside decks and forecastle

Operational controls carried out

- Communication equipment
- Emergency fire pump
- Emergency generator
- Emergency steering
- 15 ppm OWS tested

Deficiencies :

- Ship's certificates and documents , Continuous synopsis record

[Back to list](#)

Disclaimer:

The Paris MOU (its member authorities, the secretariat and the SIRENaC manager) will not be held liable for any loss, damage, or harm resulting from the use of information contained in this database, or of any reliance on its accuracy, completeness or timeliness.



Hosted by DSI - France - version : R1-4-1