

[Home](#)**Inspections**[Detentions](#)[Bannings](#)[Appeal procedure](#)[Target Factor](#)[Facts & Figures](#)[New inspection regime](#)[Inspection Database](#)[Inspection database](#) | [Inspection details](#)**NIBE MAERSK****Inspection details :**Date of first boarding : **21/09/2009**Date of final boarding : **22/09/2009**Port of inspection : **Nantes-Saint Nazaire (PA), France.**Type of inspection : **More detailed inspection**Nb of deficiency(ies) : **0****Ship's particulars at the time of inspection :**IMO number : **9322700**Name : **NIBE MAERSK**Flag : **Denmark**Callsign : **OXGY2**Ship type : **Chemical tanker**Gross tonnage : **12105**Keel date : **2006****Classification society :**

- Class certificate issued by Det Norske Veritas (DNVC), classification society responsible for issuance of class certificate as at date of first boarding

- Class certificate issued by Det Norske Veritas (DNVC), classification society responsible for issuance of class certificate as at date of first boarding

**Statutory certificates :**

- Tonnage certificate is issued by Det Norske Veritas (DNVC)

- International ship security certificate is issued by Det Norske Veritas (DNVC)
- International Air Pollution Prevention Cert is issued by Det Norske Veritas (DNVC) last survey in Spain on 09/02/2009 by Det Norske Veritas (DNVC)
- Cargo ship safety equipment is issued by Det Norske Veritas (DNVC) last survey in Spain on 09/02/2009 by Det Norske Veritas (DNVC)
- Cargo ship safety construction is issued by Det Norske Veritas (DNVC) last survey in Spain on 09/02/2009 by Det Norske Veritas (DNVC)
- Oil pollution prevention (iopp) is issued by Det Norske Veritas (DNVC) last survey in Spain on 09/02/2009 by Det Norske Veritas (DNVC)
- Danger.chemical bulk cof/ibc-code is issued by Det Norske Veritas (DNVC) last survey in Spain on 09/02/2009 by Det Norske Veritas (DNVC)
- Load lines certificates is issued by Det Norske Veritas (DNVC) last survey in Spain on 09/02/2009 by Det Norske Veritas (DNVC)
- Cargo ship safety radio is issued by Det Norske Veritas (DNVC) last survey in Spain on 09/02/2009 by Det Norske Veritas (DNVC)

#### Ship manager

- Moller-Maersk AS, Denmark

#### Charterer

- TOTAL, ., GENEVA, Switzerland

#### Areas inspected :

- Accommodation and galley
- Engine and steering room
- Navigation bridge
- Outside decks and forecastle

#### Operational controls carried out

- Communication equipment
- Emergency steering
- 15 ppm OWS tested

#### [Back to list](#)

#### Disclaimer:

The Paris MOU (its member authorities, the secretariat and the SIRENaC manager) will not be held liable for any loss, damage, or harm resulting from the use of information contained in this database, or of any reliance on its accuracy, completeness or timeliness.



Hosted by DSI - France - version : RI-4-1