

## MANX LION

### Inspection details :

Date of first boarding : **17/08/2009**  
Date of final boarding : **17/08/2009**  
Port of inspection : **Setubal, Portugal.**  
Type of inspection : **Initial inspection**  
Nb of deficiency(ies) : **0**

### Ship's particulars at the time of inspection :

IMO number : **9163984**  
Name : **MANX LION**  
Flag : **Antigua and Barbuda**  
Callsign : **V2PQ6**  
Ship type : **Containership**  
Gross tonnage : **11153**  
Keel date : **1997**

### Classification society :

- Class certificate issued by Det Norske Veritas (DNVC), classification society responsible for issuance of class certificate as at date of first boarding

### Statutory certificates :

- International Anti-fouling System Certificate is issued by Germanischer Lloyd (GL)
- Cargo ship safety equipment is issued by Det Norske Veritas (DNVC)
- Safety management certificat (SMC) is issued by Det Norske Veritas (DNVC)
- International sewage pollution prevention certific is issued by Det Norske Veritas (DNVC)
- Doc.of compliance dangerous goods is issued by Det Norske Veritas (DNVC)
- International ship security certificate is issued by Germanischer Lloyd (GL)
- International Air Pollution Prevention Cert is issued by Det Norske Veritas (DNVC) last survey in Netherlands on 03/06/2009 by Det Norske Veritas (DNVC)
- Oil pollution prevention (iopp) is issued by Det Norske Veritas (DNVC) last survey in Netherlands on 03/06/2009 by Det Norske Veritas (DNVC)
- Load lines certificates is issued by Det Norske Veritas (DNVC) last survey in Netherlands on 03/06/2009 by Det Norske Veritas (DNVC)
- Cargo ship safety construction is issued by Det Norske Veritas (DNVC) last survey in Netherlands on 03/06/2009 by Det Norske Veritas (DNVC)
- Cargo ship safety radio is issued by Det Norske Veritas (DNVC) last survey in Netherlands on 03/06/2009 by Det Norske Veritas (DNVC)
- Document of compliance (DoC) is issued by Det Norske Veritas (DNVC) last survey in Man,Isle of,UK on 02/10/2008 by Det Norske Veritas (DNVC)

### Ship manager

- Scott Shipping Management Ltd, United Kingdom

### Areas inspected :

- Accommodation and galley
- Engine and steering room
- Navigation bridge

**Disclaimer:**

The Paris MOU (its member authorities, the secretariat and the SIRENaC manager) will not be held liable for any loss, damage, or harm resulting from the use of information contained in this database, or of any reliance on its accuracy, completeness or timeliness.

---



*Hosted by DSI - France - version : R1-4-1*