

[Home](#)**[Inspections](#)**[Detentions](#)[Bannings](#)[Appeal procedure](#)[Target Factor](#)[Facts & Figures](#)[New inspection regime](#)[Inspection Database](#)[Inspection database](#) | [Inspection details](#)**JOAN****Inspection details :**

Date of first boarding : **09/09/2009**
Date of final boarding : **09/09/2009**
Port of inspection : **Mongstad, Norway.**
Type of inspection : **Initial inspection**
Nb of deficiency(ies) : **0**

Ship's particulars at the time of inspection :

IMO number : **9448877**
Name : **JOAN**
Flag : **Hong Kong,China**
Callsign : **VRFC6**
Ship type : **Tanker**
Gross tonnage : **3450**
Keel date : **2009**

Classification society :

- Class certificate issued by Nippon Kaiji Kyokai (NKK), classification society responsible for issuance of class certificate as at date of first boarding

Statutory certificates :

- International Anti-fouling System Certificate is issued by Nippon Kaiji Kyokai (NKK)
- International Air Pollution Prevention Cert is issued by Nippon Kaiji Kyokai (NKK)

- Cargo ship safety equipment is issued by Nippon Kaiji Kyokai (NKK)
- Safety management certificat (SMC) is issued by Det Norske Veritas (DNVC)
- Liquefied gas in bulk cof/igc-code is issued by Nippon Kaiji Kyokai (NKK)
- Oil pollution prevention (iopp) is issued by Nippon Kaiji Kyokai (NKK)
- Tonnage certificate is issued by Nippon Kaiji Kyokai (NKK)
- International ship security certificate is issued by Det Norske Veritas (DNVC)
- International sewage pollution prevention certific is issued by Nippon Kaiji Kyokai (NKK)
- Poll.prevent.noxious liquid subst is issued by Nippon Kaiji Kyokai (NKK)
- Load lines certificates is issued by Nippon Kaiji Kyokai (NKK)
- Cargo ship safety construction is issued by Nippon Kaiji Kyokai (NKK)
- Cargo ship safety radio is issued by Nippon Kaiji Kyokai (NKK)
- Document of compliance (DoC) is issued by Det Norske Veritas (DNVC) last survey in Belgium on 28/11/2008 by Det Norske Veritas (DNVC)

Ship manager

- Exmar Shipmanagement NV, Belgium

Charterer

- StatoilHydro, N-4035 Stavanger, Norway

Areas inspected :

- Accommodation and galley
- Engine and steering room
- Navigation bridge

[Back to list](#)

Disclaimer:

The Paris MOU (its member authorities, the secretariat and the SIRENaC manager) will not be held liable for any loss, damage, or harm resulting from the use of information contained in this database, or of any reliance on its accuracy, completeness or timeliness.



Hosted by DSI - France - version : RI-4-1