

Public Site Inspection Portlet(1.5.2.1@24.01.2011_14:51)

Search

Inspections

Details

Ship Details					
IMO Number	9346689	Name	FEHN ANTARES	Flag	Antigua and Barbuda
Type	General cargo/multipurpose	Gross Tonnage	2984	Keel Laying Date	01/01/2006 5 Years

ISM Company			
IMO Number	5078256	Address	Country
Name	Fehn Bereederungs GmbH & Co KG	City	

Charterers				
Type	Name	Address	City	Country
Time charterer	APOLLO SGIPPING GmdH&Co.KG			Germany

Class Certificates		
issuingAuthority	issue date	expiry date
BV	26/08/2008	29/04/2013

Statutory Certificates						
Certificate	Issuing authority	issue date	expiry date	Surveying authority	Date of last survey	Place of last survey
Minimum Safe Manning Document	Antigua and Barbuda	30/07/2008	29/07/2010			
International Anti-Fouling System	BV	30/07/2008	01/01/9999			
Cargo Ship Safety Construction	BV	26/08/2008	29/04/2013	BV	22/05/2009	Poland
Cargo Ship Safety Radio	BV	26/08/2008	29/04/2013	BV	22/05/2009	Poland
Prevention of Pollution by Oil	BV	26/08/2008	29/04/2013	BV	22/05/2009	Poland
International Air Pollution Prevention	BV	26/08/2008	29/04/2013	BV	22/05/2009	Poland
International Sewage Pollution Prevention	BV	26/08/2008	29/04/2013			
Load Line	BV	26/08/2008	29/04/2013	BV	22/05/2009	Poland
Document of Compliance Dangerous Goods	BV	26/08/2008	29/04/2013			
Document of Compliance	BV	16/10/2008	13/11/2013			
Tonnage	BV	30/10/2008				
International Ship Security	BV	26/05/2009	18/01/2014			
Cargo Ship Safety Equipment	BV	27/07/2009	29/04/2013			

Inspection Details					
Type of Inspection	PSC - More Detailed Inspection	Date of first visit	12/03/2010	Nb. of Deficiencies	17
Place of Inspection	Bayonne	Data of final visit	12/03/2010	Nb. of Deficiencies ground for detention	3

Inspected Areas	
Inspected Areas	Accommodation and galley Engine and steering room Navigation bridge Outside decks and forecastle

Operational Controls	
Operational Controls Carried Out	Emergency fire pump

Deficiencies				
Area	Defective item	Nature of defect	Ground for detention	RO Related
Pollution prevention - Marpol Annex I	14108 - 15 PPM Alarm arrangmts.	Not as required	No	No
Propulsion and auxiliary machinery	13101 - Propulsion main engine	Not as required	No	No
Living and Working Conditions - Living Conditions	09106 - Sanitary Facilities	Damaged	No	No
Living and Working Conditions - Working Conditions	09215 - Other (working space ILO)	Other	No	No
Living and Working Conditions - Working Conditions	09209 - Electrical	Unsafe	No	No
Living and Working Conditions - Working Conditions	09203 - Lighting (Working spaces)	Incomplete	No	No
Pollution prevention - Marpol Annex I	14108 - 15 PPM Alarm arrangmts.	Not as required	No	No
Propulsion and auxiliary machinery	13107 - Other (machinery)	Other	No	No
Propulsion and auxiliary machinery	13101 - Propulsion main engine	Not as required	No	No
Propulsion and auxiliary machinery	13101 - Propulsion main engine	Not as required	No	No
Propulsion and auxiliary machinery	13104 - Bilge pumping arrangements	Inoperative	No	No
Propulsion and auxiliary machinery	13101 - Propulsion main engine	Not as required	No	No
Living and Working Conditions - Working Conditions	09215 - Other (working space ILO)	Other	No	No
Living and Working Conditions - Living Conditions	09104 - Heating	Underheated	Yes	No
Living and Working Conditions - Working Conditions	09232 - Cleanliness of engine room	Insufficient	Yes	No
Propulsion and auxiliary machinery	13102 - Auxiliary engine	Not as required	Yes	No
Living and Working Conditions - Working Conditions	09209 - Electrical	Unsafe	No	No

Detention Details			
Reason	Date of Detention	12/03/2010	
Allowed to proceed to agreed repair yard	Date of Release	12/03/2010	

Refusal Of Access	
inspection led to refusal of access	
Reason	