

CAP FORMENTOR

Inspection details :

Date of first boarding : **03/11/2009**
Date of final boarding : **03/11/2009**
Port of inspection : **Rouen (PA), France.**
Type of inspection : **More detailed inspection**
Nb of deficiency(ies) : **0**

Ship's particulars at the time of inspection :

IMO number : **9108829**
Name : **CAP FORMENTOR**
Flag : **Spain**
Callsign : **ECKR**
Ship type : **General cargo - multipurpose ship**
Gross tonnage : **3443**
Keel date : **1995**

Classification society :

- Class certificate issued by Germanischer Lloyd (GL), classification society responsible for issuance of class certificate as at date of first boarding

Ship manager

- Alcudia Maritimos, De Alcudia S. A. C/Teodora Lanet, 26 07410, Puerto De Alcudia, Spain

Areas inspected :

- Accommodation and galley
- Engine and steering room
- Navigation bridge

Operational controls carried out

- Communication equipment
- Emergency steering
- Other

[Back to list](#)

Disclaimer:

The Paris MOU (its member authorities, the secretariat and the SIRENaC manager) will not be held liable for any loss, damage, or harm resulting from the use of information contained in this database, or of any reliance on its accuracy, completeness or timeliness.



Hosted by DSI - France - version : R1-4-1