

on Port State Control



What's new

Organisation

Publications

Contact

Links

Members

Home

Inspections

Detentions

Bannings

Appeal procedure

Target Factor

Facts & Figures

New inspection regime

Inspection Database

Inspection database | Inspection details

KARSOY

Inspection details:

Date of first boarding: **01/02/2010**Date of final boarding: **02/02/2010**

Port of inspection: Rostock, Germany.

Type of inspection: Initial inspection

Nb of deficiency(ies): 0

Ship's particulars at the time of inspection:

IMO number: 9555618
Name: KARSOY
Flag: Turkey
Callsign: TCXR3

Ship type: **General cargo - multipurpose ship**

Gross tonnage: **7635**Keel date: **2008**

Classification society:

- Class certificate issued by Bureau Veritas (BV), classification society responsable for issuance of class certificate as at date of first boarding

Statutory certificates:

- International Anti-fouling System Certificate is issued by Bureau Veritas (BV)
- Engine International Air Pollution Prevention Cert is issued by Bureau Veritas (BV)
- Continuous Synopsis Record is issued by Bureau Veritas (BV)

- (BV) last survey in Belgium on 17/08/2009 by Bureau Veritas (BV)
- Danger.chemical bulk cof/ibc-code is issued by Bureau Veritas (BV) last survey in Belgium on 17/08/2009 by Bureau Veritas (BV)
- Oil pollution prevention (iopp) is issued by Bureau Veritas (BV) last survey in Belgium on 17/08/2009 by Bureau Veritas (BV)
- Document of compliance (DoC) is issued by Det Norske Veritas (DNVC) last survey in Switzerland on 16/12/2008 by Det Norske Veritas (DNVC)
- Safety management certificat (SMC) is issued by Bureau Veritas (BV) last survey in Belgium on 18/11/2008 by Bureau Veritas (BV)
- International ship security certificate is issued by Bureau Veritas (BV) last survey in Belgium on 18/11/2008 by Bureau Veritas (BV)
- Cargo ship safety radio is issued by Bureau Veritas (BV) last survey in United Kingdom on 10/10/2008 by Bureau Veritas (BV)

Ship manager

- ABC Maritime AG, 1 Rue Perdtemps CH-1260, Nyon, Switzerland

Areas inspected:

- Accommodation and galley
- Engine and steering room
- Navigation bridge

Back to list

Disclaimer:

The Paris MOU (its member authorities, the secretariat and the SIReNaC manager) will not be held liable for any loss, damage, or harm resulting from the use of information contained in this database, or of any reliance on its accuracy, completeness or timeliness.



Hosted by DSI - France - version: R1-4-1