



on Port State Control



[What's new](#) [Organisation](#) [Publications](#) [Contact](#) [Links](#) [Members](#)

[Home](#)

[Inspections](#)

[Detentions](#)

[Bannings](#)

[Appeal procedure](#)

[Target Factor](#)

[Facts & Figures](#)

[New inspection regime](#)

Inspection Database

[Inspection database](#) | [Inspection details](#)

LARCH

Inspection details :

Date of first boarding : **15/09/2009**

Date of final boarding : **15/09/2009**

Port of inspection : **Szczecin, Poland.**

Type of inspection : **Initial inspection**

Nb of deficiency(ies) : **3**

Ship's particulars at the time of inspection :

IMO number : **8415689**

Name : **LARCH**

Flag : **Antigua and Barbuda**

Callsign : **V2VR**

Ship type : **General cargo - multipurpose ship**

Gross tonnage : **2119**

Keel date : **1984**

Classification society :

- Class certificate issued by Germanischer Lloyd (GL), classification society responsible for issuance of class certificate as at date of first boarding

Statutory certificates :

- International Air Pollution Prevention Cert is issued by

Germanischer Lloyd (GL)

- Cargo ship safety equipment is issued by Germanischer Lloyd (GL)
- Cargo ship safety construction is issued by Germanischer Lloyd (GL)
- Load lines certificates is issued by Germanischer Lloyd (GL)
- Oil pollution prevention (iopp) is issued by Germanischer Lloyd (GL)
- International sewage pollution prevention certific is issued by Germanischer Lloyd (GL)
- Tonnage certificate is issued by Germanischer Lloyd (GL)
- Cargo ship safety radio is issued by Germanischer Lloyd (GL)
- Document of compliance (DoC) is issued by Lloyd's Register (LR) last survey in Netherlands on 07/08/2009 by Lloyd's Register (LR)
- Safety management certificat (SMC) is issued by Lloyd's Register (LR) last survey in Ireland on 29/05/2009 by Lloyd's Register (LR)
- International ship security certificate is issued by Lloyd's Register (LR) last survey in Ireland on 29/05/2009 by Lloyd's Register (LR)

Ship manager

- Nyki Shipping BV, Netherlands

Areas inspected :

- Accommodation and galley
- Engine and steering room
- Navigation bridge
- Outside decks and forecastle

Deficiencies :

- ISM related deficiencies, Development of plans for shipboard operations
- Load lines , Windows, side scuttles
- MARPOL annex I, Oil record book

[Back to list](#)

Disclaimer:

The Paris MOU (its member authorities, the secretariat and the SIRENaC manager) will not be held liable for any loss, damage, or harm resulting from the use of information contained in this database, or of any reliance on its accuracy, completeness or timeliness.