

LEA

Inspection details :

Date of first boarding : **02/04/2007**
Date of final boarding : **03/04/2007**
Port of inspection : **Szczecin, Poland.**
Type of inspection : **Initial inspection**
Nb of deficiency(ies) : **6**

Ship's particulars at the time of inspection :

IMO number : **7032258**
Name : **LEA**
Flag : **Sweden**
Callsign : **SLGO**
Ship type : **General cargo - multipurpose ship**
Gross tonnage : **1345**
Keel date : **1970**

Classification society :

- Class certificate issued by Germanischer Lloyd (GL), classification society responsible for issuance of class certificate as at date of first boarding

Statutory certificates :

- International Air Pollution Prevention Cert is issued by Germanischer Lloyd (GL)
- Cargo ship safety construction is issued by Germanischer Lloyd (GL) last survey in Denmark on 08/06/2006 by Germanischer Lloyd (GL)
- Load lines certificates is issued by Germanischer Lloyd (GL) last survey in Denmark on 08/06/2006 by Germanischer Lloyd (GL)

Ship manager

- rederi AB LEA, Trådgårdsmästervågen 17, SE 590-95 Loftahammer, Sweden

Areas inspected :

- Accommodation and galley
- Engine and steering room
- Navigation bridge
- Outside decks and forecastle

Operational controls carried out

- Emergency steering

Deficiencies :

- Accident prevention (ILO147), Warning notices
- Life saving appliances , On board training and instructions
- Propulsion & aux., Cleanliness of engine room
- Safety of navigation, Nautical publications
- Ship's certificates and documents , Other (certificates)
- Structural safety, Beams, frames, floors-corrosion

Disclaimer:

The Paris MOU (its member authorities, the secretariat and the SIRENaC manager) will not be held liable for any loss, damage, or harm resulting from the use of information contained in this database, or of any reliance on its accuracy, completeness or timeliness.



Hosted by DSI - France - version : R1-4-1