



on Port State Control



What's new Organisation Publications Contact Links Members

[Home](#)

[Inspections](#)

[Detentions](#)

[Bannings](#)

[Appeal procedure](#)

[Target Factor](#)

[Facts & Figures](#)

[New inspection regime](#)

[Inspection Database](#)

[Inspection database](#) | [Inspection details](#)

SALIH CIHAN

Inspection details :

Date of first boarding : **19/12/2008**

Date of final boarding : **19/12/2008**

Port of inspection : **Seville, Spain.**

Type of inspection : **Initial inspection**

Nb of deficiency(ies) : **0**

Ship's particulars at the time of inspection :

IMO number : **9423853**

Name : **SALIH CIHAN**

Flag : **Turkey**

Callsign : **TCTF2**

Ship type : **General cargo - multipurpose ship**

Gross tonnage : **5574**

Keel date : **2006**

Classification society :

- Class certificate issued by Bureau Veritas (BV), classification society responsible for issuance of class certificate as at date of first boarding

Statutory certificates :

- International Air Pollution Prevention Cert is issued by

Bureau Veritas (BV)

- Document of compliance (DoC) is issued by Bureau Veritas (BV)
- Safety management certificat (SMC) is issued by Bureau Veritas (BV)
- Load lines certificates is issued by Bureau Veritas (BV)
- Oil pollution prevention (iopp) is issued by Bureau Veritas (BV)
- International sewage pollution prevention certific is issued by Bureau Veritas (BV)

Ship manager

- Cihan Denizcilik Petrol, 61, Kat.2 Yenishara Kadikoy, ISTAMBUL, Turkey

Areas inspected :

- Accommodation and galley
- Navigation bridge
- Outside decks and forecastle

[Back to list](#)

Disclaimer:

The Paris MOU (its member authorities, the secretariat and the SIRENaC manager) will not be held liable for any loss, damage, or harm resulting from the use of information contained in this database, or of any reliance on its accuracy, completeness or timeliness.



Hosted by DSI - France - version : R1-4-1